

	A	B	C	D	E
1	Date	Employee	WO	Location	Work Performed
2	08-Nov-18	NISBET; ERIC W.	48896	CIMS - QUINCY	QUINCY PD SERVER UPGRADE
3	06-Nov-18	REX II; JAMES D	50152	CIMS - BOSTON	Onsite at bfd 18 found the ups plugged in behind couch was knocked out--plug back in ups charging/equipment back up-add power strip on shelf -plug back in ups charging/equipment back up -add power strip on shelf
4	06-Nov-18	WASHBURN; GREGORY R	50152	CIMS - BOSTON	BFD DOT AVE RADIO DOWN-Found that behind couch UPS came unplugged from wall outlet
5	07-Nov-18	PAPPAS; SEAN M	50224	CIMS - CHELSEA	These 2 sites Chelsea Walk Pub and Broadway & 4th needed to be taken down due to the poles being moved. They have been temporarily removed until the new poles are installed. Leave ticket open.
6	04-Nov-18	WASHBURN; GREGORY R	50266	CIMS - BOSTON	Washington & Essex PTZ-PTZ was down Power reset done, cam back up
7	09-Nov-18	REX II; JAMES D	50266	CIMS - BOSTON	CIMS BOSTON Washington & Essex PTZ-Replaced PTZ, also changed IP on cam
8	09-Nov-18	WASHBURN; GREGORY R	50266	CIMS - BOSTON	CIMS BOSTON Washington & Essex PTZ-Replaced PTZ, also changed IP on cam

	F	G	H	I	J	K
1	Employee Type	Hours	Pay_ID	Rate	Total	
2	Software Technician	6	REG	125	\$750.00	
3	Technician Programmer	2	REG	109	\$218.00	
4	Technician Programmer	2	REG	109	\$218.00	
5	Technician Programmer	1.5	OT	125	\$187.50	
6	Technician Programmer	1	DT	159	\$159.00	
7	Technician Programmer	2	REG	109	\$218.00	
8	Technician Programmer	2	REG	109	\$218.00	

	A	B	C	D	E
9	04-Nov-18	WASHBURN; GREGORY R	50267	CIMS - BOSTON	Day 1 of 3-KNEELAND & TYLER 3X CAMS DOWN-Power reset done brought link back up
10	05-Nov-18	REX II; JAMES D	50267	CIMS - BOSTON	Day 2 of 3-replace radio/injector/new cat5 ends
11	05-Nov-18	WASHBURN; GREGORY R	50267	CIMS - BOSTON	Day 2 of 3-Radio down, replaced Station Radio
12	07-Nov-18	REX II; JAMES D	50267	CIMS - BOSTON	Day 3 of 3-link went down again, replace 2nd radio at Harrison, set lock to Mac at Tyler-new cell pole placed 60ft away possibly causing issue
13	07-Nov-18	REX II; JAMES D	50267	CIMS - BOSTON	Day 3 of 3-link dropped after two hours-replace kneeland radio with new, move radio to adjacent pole for perfect LOS-change chnl size-monitor while onsite checking for anomalies
14	07-Nov-18	WASHBURN; GREGORY R	50267	CIMS - BOSTON	Day 3 of 3-link went down again, replace 2nd radio at Harrison, set lock to Mac at Tyler-new cell pole placed 60ft away possibly causing issue
15	07-Nov-18	WASHBURN; GREGORY R	50267	CIMS - BOSTON	Day 3 of 3-Link down again, Changed all cabling changed freq ch and size. replaced AP with new radio. monitored onsite for 1.5hrs
16	04-Nov-18	WASHBURN; GREGORY R	50268	CIMS - BOSTON	BOSTON JOY ST 2X CAMS-Heavy wind had shifted Radios on top of Ritz. Realigned and tightened up and re-aligned all equipment.
17	05-Nov-18	PAPPAS; SEAN M	50276	CIMS - BOSTON	WOODGATE & STANDARD-The PTZ function didn't work on this camera from the server. Was able to get it to work locally at the camera but it was lagging pretty bad. Going to have to monitor it and possibly change out cam if it doesn't change. CLOSE TICKET
18	05-Nov-18	WHITCOMB; SCOTT M	50276	CIMS - BOSTON	WOODGATE & STANDARD-The PTZ function didn't work on this camera from the server. Was able to get it to work locally at the camera but it was lagging pretty bad. Going to have to monitor it and possibly change out cam if it doesn't change. CLOSE TICKET
19	08-Nov-18	REX II; JAMES D	50334	CIMS - BOSTON	Day 1 of 2-add mimosa at 159 tafts ave for Long island link, change nano to dish to improve tafts location, Config radio B5 and ubnt dish
20	08-Nov-18	WASHBURN; GREGORY R	50334	CIMS - BOSTON	-change nano to dish to improve tafts location
21	09-Nov-18	REX II; JAMES D	50334	CIMS - BOSTON	Day 1 of 2-add mimosa at 159 tafts ave for Long island link, change nano to dish to improve tafts location-change nano to dish to improve tafts location
22	09-Nov-18	WASHBURN; GREGORY R	50334	CIMS - BOSTON	Day 2 of 2-Boat ride to Long Island, Installed B5 radio and custom mount for water tower mount.
23	09-Nov-18	WASHBURN; GREGORY R	50334	CIMS - BOSTON	Day 2 of 2-Boat ride to Long Island, Installed B5 radio and custom mount for water tower mount.
24	07-Nov-18	NISBET; ERIC W.	50376	CIMS - BOSTON	Added patch to all archivers and directory server to eliminate the Transcoder issues.
25	14-Nov-18	PAPPAS; SEAN M	50024	CIMS - REVERE	BPD CIMS Quincy PD work on vidio output for main workstation and vidio monitors per Joe P
26	14-Nov-18	PAPPAS; SEAN M	50024	CIMS - REVERE	Connected the cat5 and the 24v power supply to the PTZ at Bell Circle, and landed it on the server. This cam is now up and recording.
27	15-Nov-18	PAPPAS; SEAN M	50024	CIMS - REVERE	Wired and connected the PTZ at wonderland circle. Landed it and focused it. The camera is now up an running
28	14-Nov-18	NISBET; ERIC W.	50376	CIMS - BOSTON	Archivers are running out of space due to increased camera load. I had an older server with 25TB of storage on it that I had just gotten repaired by Dell. I loaded the OS, software, did updates, and then took it to Schroeder plaza and installed it. It
29	13-Nov-18	REX II; JAMES D	50453	CIMS - CHELSEA	Day 1 of 2-Multiple issues with cameras offline due to password changes on Saturday
30	13-Nov-18	WASHBURN; GREGORY R	50453	CIMS - CHELSEA	Day 1 of 2-Multi issue resolved along with fixing password changes done.
30	15-Nov-18	REX II; JAMES D	50453	CIMS - CHELSEA	Day 2 of 2-Remote troubleshooting/radio check

	F	G	H	I	J	K
9	Technician Programmer	1	DT	159	\$159.00	
10	Technician Programmer	1	OT	125	\$125.00	
11	Technician Programmer	1	OT	125	\$125.00	
12	Technician Programmer	1	REG	109	\$109.00	
13	Technician Programmer	2	OT	125	\$250.00	
14	Technician Programmer	1	REG	109	\$109.00	
15	Technician Programmer	2	OT	125	\$250.00	
16	Technician Programmer	2	DT	159	\$318.00	
17	Technician Programmer	2	REG	109	\$218.00	
18	Technician Programmer	2	REG	109	\$218.00	
19	Technician Programmer	4	REG	109	\$436.00	
20	Technician Programmer	2	REG	109	\$218.00	
21	Technician Programmer	6	REG	109	\$654.00	
22	Technician Programmer	6	REG	109	\$654.00	
23	Software Technician	8	REG	125	\$1,000.00	
24	Software Technician	8	REG	125	\$1,000.00	
25	Technician Programmer	2	OT	125	\$250.00	
26	Technician Programmer	2.5	OT	125	\$312.50	
27	Software Technician	6	REG	125	\$750.00	
28	Technician Programmer	2	OT	125	\$250.00	
29	Technician Programmer	2	OT	125	\$250.00	
30	Technician Programmer	1	REG	109	\$109.00	

	A	B	C	D	E
31	15-Nov-18	WASHBURN; GREGORY R	50453	CIMS - CHELSEA	Day 2 of 2-Report of 3 cams froze. found that 2 radios on E.Boston side took a power hit the night prior. (Possible bridge inspection crew tripped a breaker?) video was back up but had to be dragged back over in cntrl center bridge crew does not have access to. Also found 2 cameras unable to record. fixed in Server, also reboot of main server. monitored with Bridge crew for 30min after work.
32	15-Nov-18	WASHBURN; GREGORY R	50453	CIMS - CHELSEA	Day 2 of 2-Report of 3 cams froze. found that 2 radios on E.Boston side took a power hit the night prior. (Possible bridge inspection crew tripped a breaker?) video was back up but had to be dragged back over in cntrl center bridge crew does not have access to. Also found 2 cameras unable to record. fixed in Server, also reboot of main server. monitored with Bridge crew for 30min after work.
33	15-Nov-18	REX II; JAMES D	50486	CIMS - BROOKLINE	install mast/new cable at NEBH -install ubnt link to replace ptp54300
34	15-Nov-18	SAVAGE;MARK	50486	CIMS - BROOKLINE	Brookline - Aspinwall- NEBH radio upgrade -NE Baptist installed new Mast and , New cabling installed UBNT dish took down old PTP. Aspinwall- Installed this remote site With UBNT Dish. took down old ptp.
35	15-Nov-18	WASHBURN; GREGORY R	50486	CIMS - BROOKLINE	NE Baptist installed new Mast and , New cabling installed UBNT dish took down old PTP. Aspinwall- Installed this remote site With UBNT Dish. took down old ptp.
36	15-Nov-18	REX II; JAMES D	50521	CIMS - BOSTON	Radio link down affecting x 9 cams on milk street- onsite found radio unreachable via ip-factory reset,default ip pingable but no web GUI-replace radio and cabling
37	17-Nov-18	PAPPAS; SEAN M	50537	CIMS - REVERE	Sigourney & Squire Rd. This camera wasn't showing video. I went to the site to find that the phoenix connector disconnected form the camera. I re terminated the connector and plugged it back in. The camera is back up and working properly.
38	17-Nov-18	PAPPAS; SEAN M	50538	CIMS - EVERETT	Everett City Hal-The camera and the radio were down at this site. the radio had disassociated form the AP on the Whidden roof. I changed out to the radio link and configured it to work with the AP on . The sit is back up and working properly.
39	17-Nov-18	PAPPAS; SEAN M	50539	CIMS - WINTHROP	DEER ISLAND-The 2 fixed cameras were down at this site. They are recording in Boston and view able in Winthrop. They were power cycled and came back up on Boston. New licenses need to be ordered for Winthrop to re land them on the server. CLOSE TICKET
40	16-Nov-18	PAPPAS; SEAN M	50540	CIMS - WINTHROP	The radio at Main st and Pleasant st was down and disassociated from the AP. This affected multiple cameras. After rebooting the radio the link still didn't re associate with the AP. I had to go to Banks st where the AP was located and reboot th
41	17-Nov-18	SAVAGE;MARK	50542	CIMS - QUINCY	Day 1 of 2-Quincy trouble shoot 14 cameras down- Repoet that cams were down form Joe P QPD IT . Worked thorough list and restored all but 2 QPD aware
42	17-Nov-18	WASHBURN; GREGORY R	50546	CIMS - BOSTON	Washington & Franklin-This site found no power, found that millennium tower engineering had been resetting breakers for the christmas lights. which power to this pole comes from. reset back on and power was restored. also had to do a manual reboot
43	17-Nov-18	WASHBURN; GREGORY R	50547	CIMS - BOSTON	Wardman St-Arial Cat5 was cut from which appears a cut hit this. could not restrng due to traffic. need to have 2nd bucket truck here early in morning to repair.
44	17-Nov-18	WASHBURN; GREGORY R	50548	CIMS - BOSTON	Tremont &Park- Cam had ping but no GUI. manual reboot of cam came back up.

	F	G	H	I	J	K
31	Technician Programmer	1	REG	109	\$109.00	
32	Technician Programmer	1	OT	125	\$125.00	
33	Technician Programmer	3.5	REG	109	\$381.50	
34	Technician Programmer	4	REG	109	\$436.00	
35	Technician Programmer	3.5	REG	109	\$381.50	
36	Technician Programmer	2	OT	125	\$250.00	
37	Technician Programmer	1	OT	125	\$125.00	
38	Technician Programmer	2	OT	125	\$250.00	
39	Technician Programmer	2	OT	125	\$250.00	
40	Technician Programmer	2	REG	109	\$218.00	
41	Technician Programmer	6	OT	125	\$750.00	
42	Technician Programmer	2.5	OT	125	\$312.50	
43	Technician Programmer	1	OT	125	\$125.00	
44	Technician Programmer	1	OT	125	\$125.00	

	A	B	C	D	E
45	17-Nov-18	WASHBURN; GREGORY R	50549	CIMS - BOSTON	Boylston & Herreford-Moved POE port to this cam on switch. Cam back up.
46	17-Nov-18	WASHBURN; GREGORY R	50550	CIMS - BOSTON	Heatland & Whitfield-Modem is not pulling WAN IP. pulled modem to work on at shop and updated BPD of this.
47	16-Nov-18	SAVAGE;MARK	50551	CIMS - BOSTON	LAWRENCE/MASCOMA CAMERA TROUBLESHOOT-Replaced camera. Troubleshot network camera would not rediscover. took off archiver and swapped to 60. Back up and recording
48	19-Nov-18	SAVAGE;MARK	47487	CIMS - BOSTON	Day 1 of 2-QUINCY MARITIME - INSTALL 120 VOLT FOR MARITIME CAMERA REINSTALL DUE TO STORM
49	20-Nov-18	SAVAGE;MARK	47487	CIMS - BOSTON	Day 2 of 2-QUINCY MARITIME - INSTALL 120 VOLT FOR MARITIME CAMERA REINSTALL DUE TO STORM
50	19-Nov-18	PAPPAS; SEAN M	50538	CIMS - EVERETT	Had to get up on the city hall roof and align the radio to shoot down to Norwood st to get a stronger link. The link is better now.
51	23-Nov-18	SAVAGE;MARK	50542	CIMS - QUINCY	Day 2 of 2-Quincy trouble shoot 14 cameras down- Repoet that cams were down form Joe P QPD IT . Worked thorough list and fixed last 2 on list
52	23-Nov-18	SAVAGE;MARK	50542	CIMS - QUINCY	Day 2 of 2-Quincy trouble shoot 14 cameras down- Repoet that cams were down form Joe P QPD IT . Worked thorough list and fixed last 2 on list
53	19-Nov-18	REX II; JAMES D	50547	CIMS - BOSTON	Boston- Wardman St-rerun arial cable reterminate
54	19-Nov-18	SAVAGE;MARK	50547	CIMS - BOSTON	Boston- Wardman St-rerun arial cable reterminate
55	19-Nov-18	WASHBURN; GREGORY R	50547	CIMS - BOSTON	Boston- Wardman St-rerun arial cable reterminate
56	19-Nov-18	REX II; JAMES D	50550	CIMS - BOSTON	Boston- Wheatland & Whitfield Modem-Modem is not pulling WAN IP-fconfig new modem/cim/reinstall
57	19-Nov-18	WASHBURN; GREGORY R	50550	CIMS - BOSTON	Boston- Wheatland & Whitfield Modem-Modem is not pulling WAN IP-fconfig new modem/cim/reinstall
58	19-Nov-18	REX II; JAMES D	50551	CIMS - BOSTON	LAWRENCE/MASCOMA CAMERA TROUBLESHOOT-factory default/ uprev/test Lawrence mascoma ptz for rma
59	19-Nov-18	REX II; JAMES D	50565	CIMS - CHELSEA	-brdwy eastern was up--brdwy Stockton and brdwy/webster where down affecting 4 cams and eastern/crescent down -both radios facing the ground on yardarm -reattach radio mounts with banding -reset brdwy Stockton to bring up brdwy/Webster -all cams up
60	23-Nov-18	REX II; JAMES D	50565	CIMS - CHELSEA	-remote in with Pappas onsite for reboot -change channel size/frequency on eastern-Stockton link to hopefully prevent the disassociation issue after power hit
61	20-Nov-18	REX II; JAMES D	50633	CIMS - QUINCY	Day 1 of 2-QUINCY 1400 HANCOCK RADIO LINKS DOWN-onsite found wj radio factory defaulted -reconfigure, run new cable for manger radio-uprev firmware -reconfigure, run new cable for Quincy Sq radio -uprev firmware
62	20-Nov-18	WASHBURN; GREGORY R	50633	CIMS - QUINCY	Day 1 of 2-QUINCY 1400 HANCOCK RADIO LINKS DOWN-onsite found wj radio factory defaulted -reconfigure, run new cable for manger radio-uprev firmware -reconfigure, run new cable for Quincy Sq radio
63	20-Nov-18	WASHBURN; GREGORY R	50633	CIMS - QUINCY	Day 1 of 2-QUINCY 1400 HANCOCK RADIO LINKS DOWN- received traps that network was back down. was able to change Lan settings on radio and switch to get equipment back up for the night. revisit will be needed to replace -reconfigure, run new cable for Quincy Sq radio -uprev firmware
64	21-Nov-18	REX II; JAMES D	50633	CIMS - QUINCY	Day 2 of 2-replace switch,new ip -replace backhaul injector,corrosion on pins-replace manger radio and jumpers-troubleshoot duplicate ip issue
65	21-Nov-18	WASHBURN; GREGORY R	50633	CIMS - QUINCY	Day 2 of 2-Replaced 2 Radios, 3 new Cat5 to Radios, and new managed switch. Monitored and everything has stabilized.

	F	G	H	I	J	K
45	Technician Programmer	1	OT	125	\$125.00	
46	Technician Programmer	1.5	OT	125	\$187.50	
47	Technician Programmer	4	REG	109	\$436.00	
48	Technician Programmer	6	REG	109	\$654.00	
49	Technician Programmer	8	REG	109	\$872.00	
50	Technician Programmer	1	REG	109	\$109.00	
51	Technician Programmer	4	REG	109	\$436.00	
52	Technician Programmer	2	OT	125	\$250.00	
53	Technician Programmer	2.5	REG	109	\$272.50	
54	Technician Programmer	2	OT	125	\$250.00	
55	Technician Programmer	2.5	REG	109	\$272.50	
56	Technician Programmer	2	REG	109	\$218.00	
57	Technician Programmer	4	REG	109	\$436.00	
58	Technician Programmer	1	REG	109	\$109.00	
59	Technician Programmer	2.5	REG	109	\$272.50	
60	Technician Programmer	1	REG	109	\$109.00	
61	Technician Programmer	2	REG	109	\$218.00	
62	Technician Programmer	2	REG	109	\$218.00	
63	Technician Programmer	2	OT	125	\$250.00	
64	Technician Programmer	6	REG	109	\$654.00	
65	Technician Programmer	6	REG	109	\$654.00	

	A	B	C	D	E
66	21-Nov-18	WASHBURN; GREGORY R	50634	CIMS - QUINCY	Day 2 of 3-QUINCY Sq Realignment -Realigned Cams tried setting up motion detection with visual and audio alarms
67	20-Nov-18	REX II; JAMES D	50634	CIMS - QUINCY	Day 1 of 3-QUINCY -1400 Hancock-Realigned x2 cams andx1 radio link Quincy Sq cams landed-install x8 GPS devices on figurines-cams landed
68	20-Nov-18	REX II; JAMES D	50634	CIMS - QUINCY	Day 1 of 3-QUINCY -1400 Hancock-Realigned x2 cams andx1 radio link Quincy Sq cams landed-install x8 GPS devices on figurines-cams landed
69	20-Nov-18	WASHBURN; GREGORY R	50634	CIMS - QUINCY	Day 1 of 3-QUINCY -1400 Hancock-Realigned x2 cams andx1 radio link Quincy Sq cams landed-install x8 GPS devices on figurines-cams landed
70	21-Nov-18	REX II; JAMES D	50634	CIMS - QUINCY	Day 2 of 3-Replace radio at 1400 -.150/.151 radio ips causing radio to negotiate to 10mbps after 10mins -ips are not ping able on server
71	23-Nov-18	NISBET; ERIC W.	50634	CIMS - QUINCY	Day 3 of 3-QUINCY -Realigned x2 cams andx1 radio link Quincy Sq cams landed-install x8 GPS devices on figurines-cams landed helped with servger and relanding of cameras at QPD
72	23-Nov-18	PAPPAS; SEAN M	50636	CIMS - BOSTON	Broadway & Stockton Chelsea, the radio link from this site to the fire station was down. This radio link affected multiple cameras being down. Reset the radio still didn't get the link back. Had to reset the radio at the fire station as well. The link came back and the cameras came back as well. Everything is back up and recording.
73	23-Nov-18	PAPPAS; SEAN M	50636	CIMS - BOSTON	Shawmut and Kendall Boston, the PTZ wasn't showing video and the radio was down. lhad to reboot the radio to get it to link back up with the AP. The PTZ needed to be power cycled as well. Video is back up and recording.
74	23-Nov-18	WHITCOMB; SCOTT M	50636	CIMS - BOSTON	Shawmut and Kendall Boston, the PTZ wasn't showing video and the radio was down. lhad to reboot the radio to get it to link back up with the AP. The PTZ needed to be power cycled as well. Video is back up and recording.
75	23-Nov-18	WHITCOMB; SCOTT M	50636	CIMS - BOSTON	Broadway & Stockton Chelsea, the radio link from this site to the fire station was down. This radio link affected multiple cameras being down. Reset the radio still didn't get the link back. Had to reset the radio at the fire station as well. The link came back and the cameras came back as well. Everything is back up and recording.
76	01-Dec-18	PAPPAS; SEAN M	50024	CIMS - REVERE	Got the camera powered up and mounted at Revere st & NShore Rd. The radios are linked but still need the port on the switch to be activated to connect to the network.
77	30-Nov-18	PAPPAS; SEAN M	50224	CIMS - CHELSEA	broadway & 4th and Chelsea walk pub-Both poles were moved and the cameras were re installed and powered up. The radios were re associated with the AP on top of city hall. Everything is back up and working properly.
78	30-Nov-18	PAPPAS; SEAN M	50224	CIMS - CHELSEA	broadway & 4th and Chelsea walk pub-Both poles were moved and the cameras were re installed and powered up. The radios were re associated with the AP on top of city hall. Everything is back up and working properly.
79	26-Nov-18	REX II; JAMES D	50650	CIMS - CHELSEA	Broadway/trial court-onsite verify a/c power on and 24vac p/supply on 24v ok-radio lan port is working-no layer 1 to camera-drill drain hole in nema-need new camera
80	26-Nov-18	WASHBURN; GREGORY R	50650	CIMS - CHELSEA	Broadway/trial court-Power good radios up but camera dead. Camera needs to be replaced.
81	26-Nov-18	REX II; JAMES D	50651	CIMS - CHELSEA	Carter/Addison-verify a/c power on-power cycle/check link to high school-power cycle orange st hop
82	26-Nov-18	WASHBURN; GREGORY R	50651	CIMS - CHELSEA	Carter/Addison-verify a/c power on-power cycle/check link to high school-power cycle orange st hop

	F	G	H	I	J	K
66	Technician Programmer	2	REG	109	\$218.00	
67	Technician Programmer	6	REG	109	\$654.00	
68	Technician Programmer	1	OT	125	\$125.00	
69	Technician Programmer	6	REG	109	\$654.00	
70	Technician Programmer	2	REG	109	\$218.00	
71	Software Technician	3	REG	125	\$375.00	
72	Technician Programmer	2	OT	125	\$250.00	
73	Technician Programmer	2	REG	109	\$218.00	
74	Technician Programmer	2	REG	109	\$218.00	
75	Technician Programmer	2	OT	125	\$250.00	
76	Technician Programmer	3	OT	125	\$375.00	
77	Technician Programmer	1	OT	125	\$125.00	
78	Technician Programmer	2	REG	109	\$218.00	
79	Technician Programmer	1.5	REG	109	\$163.50	
80	Technician Programmer	1	REG	109	\$109.00	
81	Technician Programmer	1.5	REG	109	\$163.50	
82	Technician Programmer	1.5	REG	109	\$163.50	

	A	B	C	D	E
83	27-Nov-18	REX II; JAMES D	50703	CIMS - SOMERVILLE	remove nema enclosure and ptz from the top of 165 broadway with assistance from the city tree bucket
84	27-Nov-18	WASHBURN; GREGORY R	50703	CIMS - SOMERVILLE	remove nema enclosure and ptz from the top of 165 broadway with assistance from the city tree bucket
85	26-Nov-18	PAPPAS; SEAN M	50767	CIMS - BOSTON	Eustis & Dearborn The camera on the roof wasn't showing video. The site lost power. I followed it back to the power source. The breaker was tripped. i reset the breaker and got power back. The camera is back up and recording
86	27-Nov-18	PAPPAS; SEAN M	50768	CIMS - BOSTON	LONGFELLOW TOWER Lost power on the roof where our equipment is stored, affecting multiple cameras in the area. The electricians did a power shut down in the building that day. Once power was turned back on a couple of our radios were still hung up. had to reset them manually. Everything came back up after that and the system is working properly.
87	27-Nov-18	PAPPAS; SEAN M	50768	CIMS - BOSTON	LONGFELLOW TOWER Lost power on the roof where our equipment is stored, affecting multiple cameras in the area. The electricians did a power shut down in the building that day. Once power was turned back on a couple of our radios were still hung up. had to reset them manually. Everything came back up after that and the system is working properly.
88	28-Nov-18	PAPPAS; SEAN M	50769	CIMS - BOSTON	BEACH AND SURFACE ST-Site lost power. The GFI was tripped across the street in the BTD power can. This is where our power source was being fed from. I powered it back up and cameras are back up and recording
89	27-Nov-18	PAPPAS; SEAN M	50771	CIMS - WINTHROP	had to move the QD camera from Bellevue ave to Shirley Ave in Winthrop per request from Detective Wayne Carter. The camera is powered back up focused and working properly
90	28-Nov-18	PAPPAS; SEAN M	50772	CIMS - CHELSEA	BROADWAY AND WILLIAMS STREET-The camera went bad at this site. I had to change out the bracket on the pole and change the power source to accept the different camera. I got the new camera up and powered. It's now recording on the system.
91	18-Nov-18	SONET	50250	CIMS - BOSTON	Harrison Ave/MLK/Quincy/Columbia Rd. Trouble shoot power outages and replace photo eye
92	17-Nov-18	SONET	50687-50691	CIMS - BOSTON	Wardman St-Check overhead power and data lines hanging low. Wheatland & Whitfield St-Check 120 volt power loss, reboot modem. Boylston st & Dalton St-Check 120 volt power loss, reboot modem. A1 Commons-Check 120 volt power loss, reboot modem. Termont & Park St.-Check 120 volt power loss, reboot modem
93	02-Nov-18	SONET	50681	CIMS - BOSTON	Boylston St. & Arlington St. Remove temporary Structure for Red Sox Parafe and surrounding area
94	16-Nov-18	SONET	50682, 50685-50686	CIMS - BOSTON	Mattapan Square-Check 120 volt power at base of pole, found 20 amp circuit breaker in trip position, replace in line fuse and reset circuit breaker. Quincy City Hall-check 120 volt power at base of pole and control panel, 120 volt power ok, replace defective CCTV camera. Winthrop Main & Pleasant St.-replace 5 amp in line fuse and assembly
95	01-Nov-18	SONET	50691	CIMS - BOSTON	Boston Municipal Court-Relocate CCTV antenna temporay to accommodate roof repair
96					
97					
98					
99					

	F	G	H	I	J	K
83	Technician Programmer	2.5	REG	109	\$272.50	
84	Technician Programmer	2.5	REG	109	\$272.50	
85	Technician Programmer	1	OT	125	\$125.00	
86	Technician Programmer	1	REG	109	\$109.00	
87	Technician Programmer	2	OT	125	\$250.00	
88	Technician Programmer	1	OT	125	\$125.00	
89	Technician Programmer	3	REG	109	\$327.00	
90	Technician Programmer	2.5	OT	125	\$312.50	
91	SONET	7.75	REG	102	\$790.50	
92	SONET	27	REG	102	\$2,754.00	
93	SONET	30.75	REG	102	\$3,136.50	
94	SONET	27.7	REG	102	\$2,825.40	
95	SONET	29	REG	102	\$2,958.00	
96						
97					\$0.00	
98					\$0.00	
99	Total	353.7			\$39,329.90	

	A	B	C	D
1		LAN-TEL Communications, Inc.		
2		Billing for CIMS Project - Material Costs		
3		11.1.18		
4	Date of Service/Purchase	Location	Material Provided	Material Cost
5				
6		Nothing to Report		
7				
8				
9				
10				
11				
12			Total Material Costs	\$0.00

	A	B	C	D	E	F
1			LAN-TEL Communications, Inc.			
2			Billing for CIMS Project - Project Management Costs			
3			11.1.18			
4	Date of Service	Location	Work Performed	# Hours	Rate	Total
5		Various Locations	Check Network, Project Management, Respond to POC calls and emails		\$98.00	\$0.00
6		Various Locations	Check Network, Project Management, Respond to POC calls and emails		\$98.00	\$0.00
7		Various Locations	Check Network, Project Management, Respond to POC calls and emails		\$98.00	\$0.00
8		Various Locations	Check Network, Project Management, Respond to POC calls and emails		\$98.00	\$0.00
9		Various Locations	Check Network, Project Management, Respond to POC calls and emails		\$98.00	\$0.00
10			Total	0		\$0.00

	G
1	
2	
3	
4	Special Event, PSNET or CIMS
5	
6	
7	
8	
9	
10	

	A	B	C	D	E	F
1	November Labor Totals					
2	Labor Type	Hours	Total			
3	LAN-TEL Labor regular rate	138	\$15,042.00			
4	LAN-TEL Labor overtime rate	89.5	\$11,187.50			
5	LAN-TEL Labor double time rate	4	\$636.00			
6	LAN-TEL Labor Apprentice regular rate		\$0.00			
7	LAN-TEL Labor Apprentice overtime rate		\$0.00			
8	LAN-TEL Software Tech rate		\$0.00			
9	LAN-TEL Software Tech overtime rate		\$0.00			
10	LAN-TEL Software Tech double time rate		\$0.00			
11	Sonet	122.2	\$12,464.40			
12	Total Labor	353.7	\$39,329.90			
13						
14	Total Project Management Labor		\$0.00			
15	Total Labor & PM			\$39,329.90		\$0.00
16	November Material Totals					
17	Total PTZ DvTel Cameras	0	\$0.00			
18	Total Fixed DvTel Cameras	0	\$0.00			
19	Total Power Supplies	0	\$0.00			
20	Total Bucket Truck Rentals (LAN-TEL & Sonet)	0	\$0.00			
21	Total Adapters	0	\$0.00			
22	Total Encoders	0	\$0.00			
23	Total NEMA Enclosures	0	\$0.00			
24	Total Astro Brackets	0	\$0.00			
25	Total Antennas & Assoc. Equipment	0	\$0.00			
26	Total Cable & Assoc. Hardware	-	\$0.00			
27	Total POEs	0	\$0.00			
28	Total Misc. Equipment	-	\$0.00			
29	Total Material Used			\$0.00		
30						
31	Total Billing for November Billing			\$39,329.90		