

	A	B	C	D	E
1	Date	Employee	Location	Work Performed	Employee Type
2	01-Oct-18	REX II; JAMES D	CIMS - BOSTON Harrison and Kneeland	Accident at intersection taking out power distribution box and traffic light - remove triple head on traffic light so that can be replaced	Technician Programmer
3	01-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Harrison and Kneeland	Accident at intersection taking out power distribution box and traffic light - remove triple head on traffic light so that can be replaced	Technician Programmer
4	01-Oct-18	REX II; JAMES D	CIMS - BOSTON Blue Hill Ave	- remove ptp5400@ bhave/river/babson -install ubiquity to wood haven sector	Technician Programmer
5	01-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Blue Hill Ave	- remove ptp5400@ bhave/river/babson -install ubiquity to wood haven sector	Technician Programmer
6	01-Oct-18	SAVAGE;MARK	CIMS - REVERE Four Seasons and Malden/Revere FD	Walk thru of 3 Revere sites for additional cameras and antennae to Revere CIMs, HS, Park and Four Seasons Hotel	Technician Programmer
7	01-Oct-18	SAVAGE;MARK	CIMS - BOSTON Warren and Milk	Axis camera randomly going to home position. replaced camera with Bosch dome fixed. Camera did not land on system. Troubleshoot. Modem updated. Installed a temp axis fixed to get thru night. Next night installed a fixed dvtel fixed. Camera no good. Installed another dvtel fixed . All set	Technician Programmer
8	01-Oct-18	SAVAGE;MARK	CIMS - BOSTON Warren and Milk	Axis camera randomly going to home position. replaced camera with Bosch dome fixed. Camera did not land on system. Troubleshoot. Modem updated. Installed a temp axis fixed to get thru night. Next night installed a fixed dvtel fixed. Camera no good. Installed another dvtel fixed . All set	Technician Programmer

	F	G	H	I	J
1	Hours	Pay_ID	Rate	Total	
2	1.5	REG	\$109.00	\$163.50	
3	1.5	REG	\$109.00	\$163.50	
4	2	REG	\$109.00	\$218.00	
5	2.5	REG	\$109.00	\$272.50	
6	4	REG	\$109.00	\$436.00	
7	1	REG	\$109.00	\$109.00	
8	5	OT	\$125.00	\$625.00	

	A	B	C	D	E
9	01-Oct-18	REX II; JAMES D	CIMS - BOSTON Dot and Ash	-remove ups, intermittent	Technician Programmer
10	01-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Dot and Ash	Found dead UPS, removed and added power strip	Technician Programmer
11	02-Oct-18	REX II; JAMES D	CIMS - BOSTON Harrison and Kneeland	-reinstall triple head on traffic signal-possibly temporary	Technician Programmer
12	02-Oct-18	REX II; JAMES D	CIMS - BOSTON Harrison and Kneeland	-reinstall triple head on traffic signal-possibly temporary	Technician Programmer
13	02-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Ipswich Street	Assist Mark with Fenway Park Tower radio install	Technician Apprentice
14	02-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	Install radios and mounts at 1330.bfd	Technician Programmer
15	02-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS - BOSTON Ipswich Street	Install radios and mounts at 1330.bfd	Technician Apprentice
16	02-Oct-18	REX II; JAMES D	CIMS - BOSTON 35 NorthHampton	-check 35 NHampton roof for possible cable placement issue. JS verified we where ok	Technician Programmer
17	17-Oct-18	Sonet	CIMS Boston -Kneeland and Harrison	Install temp 120 volt power to pole due to car accident; Reconnect power to new pole	Sonet
18	03-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Ipswich Street	Install radios and mounts at 1330.bfd	Technician Apprentice
19	03-Oct-18	REX II; JAMES D	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Programmer
20	03-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Programmer
21	03-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Programmer
22	03-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Apprentice
23	03-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Warren and Milk	Axis camera randomly going to home position. replaced camera with Bosch dome fixed. Camera did not land on system. Troubleshoot. Modem updated. Installed a temp axis fixed to get thru night. Next night installed a fixed dvtel fixed. Camera no good. Installed another dvtel fixed . All set	Technician Apprentice

	F	G	H	I	J
9	2	REG	\$109.00	\$218.00	
10	1	REG	\$109.00	\$109.00	
11	1	OT	\$125.00	\$125.00	
12	4	REG	\$109.00	\$436.00	
13	8	REG	\$85.00	\$680.00	
14	7	REG	\$109.00	\$763.00	
15	8	REG	\$85.00	\$680.00	
16	1	OT	\$125.00	\$125.00	
17	8	REG	\$102.00	\$816.00	
18	1	REG	\$85.00	\$85.00	
19	3	REG	\$109.00	\$327.00	
20	1.5	OT	\$125.00	\$187.50	
21	5	REG	\$109.00	\$545.00	
22	1	REG	\$85.00	\$85.00	
23	1	REG	\$85.00	\$85.00	

	A	B	C	D	E
24	03-Oct-18	SAVAGE;MARK	CIMS - BOSTON Warren and Milk	Axis camera randomly going to home position. replaced camera with Bosch dome fixed. Camera did not land on system. Troubleshoot. Modem updated. Installed a temp axis fixed to get thru night. Next night installed a fixed dvtel fixed. Camera no good. Installed another dvtel fixed . All set	Technician Programmer
25	03-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS - BOSTON Warren and Milk	Axis camera randomly going to home position. replaced camera with Bosch dome fixed. Camera did not land on system. Troubleshoot. Modem updated. Installed a temp axis fixed to get thru night. Next night installed a fixed dvtel fixed. Camera no good. Installed another dvtel fixed . All set	Technician Apprentice
26	03-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Hancock and Bowdoin	The camera was bad on the roof of the bomb squad. I replaced it with a new camera and re landed it on the system. It's back up and recording.	Technician Programmer
27	03-Oct-18	WHITCOMB; SCOTT M	CIMS - BOSTON Hancock and Bowdoin	The camera was bad on the roof of the bomb squad. I replaced it with a new camera and re landed it on the system. It's back up and recording.	Technician Programmer
28	03-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Berkley and Boylston	Assist PAP with radio issue at Berkley/Boylston, st james, Berkley, public alley	Technician Programmer
29	03-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Berkley and Boylston	The camera was down at Berkley & Boylston. It was the radio that factory defaulted causing the camera to go down. Got the radio back up. Camera is back up and recording.	Technician Programmer
30	03-Oct-18	WHITCOMB; SCOTT M	CIMS - BOSTON Berkley and Boylston	The camera was down at Berkley & Boylston. It was the radio that factory defaulted causing the camera to go down. Got the radio back up. Camera is back up and recording.	Technician Programmer
31	04-Oct-18	SAVAGE;MARK	CIMS Boston Blue Hill Pkwy	Reinstall camera and 2 fixed on enclosure on temp pole, reconfigure antennae	Technician Programmer
32	04-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS Boston Blue Hill Pkwy	Reinstall camera and 2 fixed on enclosure on temp pole, reconfigure antennae	Technician Apprentice
33	04-Oct-18	REX II; JAMES D	CIMS - BOSTON Berkley and Boylston	The camera was down at Berkley & Boylston. It was the radio that factory defaulted causing the camera to go down. Got the radio back up. Camera is back up and recording.	Technician Programmer

	F	G	H	I	J
24	2	REG	\$109.00	\$218.00	
25	1	REG	\$85.00	\$85.00	
26	5	REG	\$109.00	\$545.00	
27	5	REG	\$109.00	\$545.00	
28	3	REG	\$109.00	\$327.00	
29	1	OT	\$125.00	\$125.00	
30	3	REG	\$109.00	\$327.00	
31	6	REG	\$109.00	\$654.00	
32	6	REG	\$85.00	\$510.00	
33	2	REG	\$109.00	\$218.00	

	A	B	C	D	E
34	05-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Apprentice
35	05-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Programmer
36	05-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Ipswich Street	-assist mark with the Fenway Park tower radio install	Technician Programmer
37	05-Oct-18	REX II; JAMES D	CIMS - BOSTON Ipswich Street	-install radios and mounts @ 1330,bfd	Technician Programmer
38	05-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	-install radios and mounts @ 1330,bfd	Technician Programmer
39	05-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS - BOSTON Ipswich Street	-install radios and mounts @ 1330,bfd	Technician Apprentice
40	06-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	-install radios and mounts @ 1330,bfd	Technician Programmer
41	09-Oct-18	NISBET; ERIC W.	CIMS - BOSTON BPD	Time Synch issues	Software Technician
42	09-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	Reviewing camera locations with Det Bruker Got NEMA box mounted and powered up at Oak Island and North Shore Rd Pole	Technician Programmer
43	09-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Ipswich Street	Install Link between 1330 Jersey/Van Ness, Cat 5 run a 1330, bring up IPS Vanessa radio, clean up Boylston Sunoco Neman, Connect to Fenway Light tower	Technician Apprentice
44	09-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	installed 2 cable runs on BFD Fire Alarm roof. Climbed light tower at Fenway and installed 60 degree sector. Reconfigured all BAA cameras with antennae to Fire alarm. Installed sled on 1330 Boylston with dish and sector. ran temp power to front of building. Added cameras to Brookline and Yawkey. Maintenance to all domes and verified stickers on all boxes. This is an ongoing job.	Technician Programmer
45	09-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	installed 2 cable runs on BFD Fire Alarm roof. Climbed light tower at Fenway and installed 60 degree sector. Reconfigured all BAA cameras with antennae to Fire alarm. Installed sled on 1330 Boylston with dish and sector. ran temp power to front of building. Added cameras to Brookline and Yawkey. Maintenance to all domes and verified stickers on all boxes. This is an ongoing job.	Technician Programmer

	F	G	H	I	J
34	6	REG	\$85.00	\$510.00	
35	8	REG	\$109.00	\$872.00	
36	1	OT	\$125.00	\$125.00	
37	8	REG	\$109.00	\$872.00	
38	8	REG	\$109.00	\$872.00	
39	8	REG	\$85.00	\$680.00	
40	8	OT	\$125.00	\$1,000.00	
41	4	REG	\$125.00	\$500.00	
42	2	OT	\$125.00	\$250.00	
43	8	REG	\$85.00	\$680.00	
44	8	REG	\$109.00	\$872.00	
45	2	OT	\$125.00	\$250.00	

	A	B	C	D	E
46	09-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS - BOSTON Ipswich Street	installed 2 cable runs on BFD Fire Alarm roof. Climbed light tower at Fenway and installed 60 degree sector. Reconfigured all BAA cameras with antennae to Fire alarm. Installed sled on 1330 Boylston with dish and sector. ran temp power to front of building. Added cameras to Brookline and Yawkey. Maintenance to all domes and verified stickers on all boxes. This is an ongoing job.	Technician Apprentice
47	10-Oct-18	NISBET; ERIC W.	CIMS - BOSTON BPD	Time Synch issues	Software Technician
48	10-Oct-18	NISBET; ERIC W.	CIMS - BOSTON Multiple	NO notes	Software Technician
49	10-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	Built out the NEMA box for the Wonderland Circle Install	Technician Programmer
50	10-Oct-18	REX II; JAMES D	CIMS - BOSTON Ipswich Street	Install Link between 1330 Jersey/Van Ness, Cat 5 run a 1330, bring up IPS Vanessa radio, clean up Boylston Sunoco Neman, Connect to Fenway Light tower	Technician Programmer
51	10-Oct-18	REX II; JAMES D	CIMS - BOSTON Ipswich Street	Install Link between 1330 Jersey/Van Ness, Cat 5 run a 1330, bring up IPS Vanessa radio, clean up Boylston Sunoco Nema, Connect to Fenway Light tower	Technician Programmer
52	10-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	Assemble 3x head camera for Brookline and Yawkey, Lansdowne camera 2 add Arial cat 5 2 bump poles install fix and poe switch, cleaned various cameras around Fenway	Technician Programmer
53	10-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	Assemble 3x head camera for Brookline and Yawkey, Lansdowne camera 2 add Arial cat 5 2 bump poles install fix and poe switch, cleaned various cameras around Fenway	Technician Programmer
54	10-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	Assemble 3x head camera for Brookline and Yawkey, Lansdowne camera 2 add Arial cat 5 2 bump poles install fix and poe switch, cleaned various cameras around Fenway	Technician Programmer
55	17-Oct-18	Sonet	CIMS Boston - Mount Vernon	Trouble with intermittenent 120 volt power at pole; relcocated cameras to a new location and rewired	Sonet
56	17-Oct-18	Sonet	CIMS Boston - Harrison Ave/MLK	Troubleshoot power outages and replace photo eye	Sonet

	F	G	H	I	J
46	8	REG	\$85.00	\$680.00	
47	3	OT	\$145.00	\$435.00	
48	4	REG	\$125.00	\$500.00	
49	2	OT	\$125.00	\$250.00	
50	8	REG	\$109.00	\$872.00	
51	2.5	OT	\$125.00	\$312.50	
52	4	REG	\$109.00	\$436.00	
53	1.5	OT	\$125.00	\$187.50	
54	8	REG	\$109.00	\$872.00	
55	28	REG	\$102.00	\$2,856.00	
56	8	REG	\$102.00	\$816.00	

	A	B	C	D	E
57	11-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	10-10-18 -Plotted out wireless locations, added radio at 1330 Boylston to hit Jersey St. Section. -Jersey and Van Ness radio replacement -172 Ipswich config radio to 1330 AP -Boylston & Ipswich Config Radio to Fenway AP and power up PTZ.	Technician Programmer
58	11-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	10-11-18 -Added Can at 55 Jersey with Fixed. -Re IP'd all equipment to go to Bonet BFD H.Q -BFD Fiber TX to Cat 5, added Switch, realigned dishes on roof. -Landed all cams. replaced 55 Jersey cam -Added all equipment on intermapper.	Technician Programmer
59	11-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	10-6-18 -Assemble 3x head cam for Brookline & Yawkey -Lansdowne Cam2 add Arial cat5 2 bump poles install fix and POE Switch. -Cleaned various cams around Fenway also	Technician Programmer
60	11-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	10-10-18 -Plotted out wireless locations, added radio at 1330 Boylston to hit Jersey St. Section. -Jersey and Van Ness radio replacement -172 Ipswich config radio to 1330 AP -Boylston & Ipswich Config Radio to Fenway AP and power up PTZ.	Technician Programmer
61	11-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	10-11-18 -Added Can at 55 Jersey with Fixed. -Re IP'd all equipment to go to Bonet BFD H.Q -BFD Fiber TX to Cat 5, added Switch, realigned dishes on roof. -Landed all cams. replaced 55 Jersey cam -Added all equipment on intermapper.	Technician Programmer
62	11-Oct-18	PAPPAS; SEAN M	CIMS - CHELSEA Highland Suffolk	This site had no power. The power source was coming from a pole across the street. The phot cell on top of the pole was damaged and needs to be replaced.	Technician Programmer

	F	G	H	I	J
57	1	OT	\$125.00	\$125.00	
58	1	OT	\$125.00	\$125.00	
59	8	REG	\$109.00	\$872.00	
60	8	REG	\$109.00	\$872.00	
61	8	REG	\$109.00	\$872.00	
62	1	OT	\$125.00	\$125.00	

	A	B	C	D	E
63	11-Oct-18	PAPPAS; SEAN M	CIMS - CHELSEA Highland Suffolk	This site had no power. The power source was coming from a pole across the street. The phot cell on top of the pole was damaged and needs to be replaced.	Technician Programmer
64	11-Oct-18	WHITCOMB; SCOTT M	CIMS - CHELSEA Highland Suffolk	This site had no power. The power source was coming from a pole across the street. The phot cell on top of the pole was damaged and needs to be replaced.	Technician Programmer
65	11-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON UMANA Barnes Roof	The PTZ was down and not showing video. Had to change out the camera for a fixed camera and it back recording video	Technician Programmer
66	11-Oct-18	WHITCOMB; SCOTT M	CIMS - BOSTON UMANA Barnes Roof	The PTZ was down and not showing video. Had to change out the camera for a fixed camera and it back recording video	Technician Programmer
67	11-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Walnut and Dale	Modem wad down and not showing video. Had to reset the modem and rediscover the camera. It's back up and recording	Technician Programmer
68	11-Oct-18	WHITCOMB; SCOTT M	CIMS - BOSTON Walnut and Dale	Modem wad down and not showing video. Had to reset the modem and rediscover the camera. It's back up and recording	Technician Programmer
69	11-Oct-18	NISBET; ERIC W.	CIMS - BOSTON BPD	Time Synch issues	Software Technician
70	11-Oct-18	NISBET; ERIC W.	CIMS - BOSTON BPD	Archiver 57 rehab	Software Technician
71	11-Oct-18	REX II; JAMES D	CIMS - BOSTON Ipswich Street	10-10-18 Install link between 1330-jersey/van ness -cat5 run at 1330 -bring up ips/Vanessa radio -clean up Boylston Sunoco nema/connect to Fenway light tower AP	Technician Programmer
72	11-Oct-18	REX II; JAMES D	CIMS - BOSTON Ipswich Street	10-11-18 Install nema/radio to 1330- bullet fixed at jersey/vanness -bfalarm re ip radios/cams to bonet	Technician Programmer
73	11-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	Assisted with the cable run and mounted the two dishes on the roof of the BFD	Technician Programmer

	F	G	H	I	J
63	1	REG	\$109.00	\$109.00	
64	1	REG	\$109.00	\$109.00	
65	4	REG	\$109.00	\$436.00	
66	4	REG	\$109.00	\$436.00	
67	3	REG	\$109.00	\$327.00	
68	3	REG	\$109.00	\$327.00	
69	4	REG	\$125.00	\$500.00	
70	2	OT	\$145.00	\$290.00	
71	8	REG	\$109.00	\$872.00	
72	8	REG	\$109.00	\$872.00	
73	8	REG	\$109.00	\$872.00	

	A	B	C	D	E
74	11-Oct-18	SAVAGE;MARK	CIMS - BOSTON Ipswich Street	Plotted out wireless locations at 1330 Boylston to hit Jersey Street Section Jersey and Van Ness radio replacement. 172 Ipswich config radio to 1330 AP. Boylston and Ipswich config radio to Fenway AP and power up PTZ	Technician Programmer
75	11-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Ipswich Street	10-6-18 -Assemble 3x head cam for Brookline & Yawkey -Lansdowne Cam2 add Arial cat5 2 bump poles install fix and POE Switch. -Cleaned various cams around Fenway also	Technician Programmer
76	12-Oct-18	REX II; JAMES D	CIMS - BOSTON Broadway and L Street	-replace derry tech radio link with ubnt/cam up	Technician Programmer
77	12-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Broadway and L Street	-replace derry tech radio link with ubnt/cam up	Technician Programmer
78	13-Oct-18	SAVAGE;MARK	CIMS - BOSTON Tremont and West Newton	NO notes	Technician Programmer
79	13-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Tremont and West Newton	NO notes	Technician Programmer
80	13-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	Mounted and powered up the box at the corner of North Shore Rd and Revere Street.	Technician Programmer
81	15-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	10/9/18- Got Nema box mounted and powered up at Oak Island and North Shore Rd pole. waiting on the camera to install.	Technician Programmer
82	15-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	10/10/18- Built out the nema box for Wonderland circle install.	Technician Programmer
83	15-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	10/13/18- Mounted and powered up the box at the corner of North Shore rd. and Revere St. Waiting on camera. Also mounted and powered up the Nema box at Wonderland Circle. Waiting on camera.	Technician Programmer
84	15-Oct-18	REX II; JAMES D	CIMS - CHELSEA	-upgrade old canopy radio with ubiquity-cpd	Technician Programmer
85	16-Oct-18	NISBET; ERIC W.	CIMS - BOSTON	Time Synch issues - nonotes	Software Technician
86	16-Oct-18	NISBET; ERIC W.	CIMS - BOSTON	BPD archiver 57 rehab	Software Technician

	F	G	H	I	J
74	2	OT	\$125.00	\$250.00	
75	1	OT	\$125.00	\$125.00	
76	2	REG	\$109.00	\$218.00	
77	1.5	REG	\$109.00	\$163.50	
78	2	OT	\$125.00	\$250.00	
79	2	OT	\$125.00	\$250.00	
80	3	OT	\$125.00	\$375.00	
81	2	OT	\$125.00	\$250.00	
82	2	OT	\$125.00	\$250.00	
83	2	OT	\$125.00	\$250.00	
84	2	REG	\$109.00	\$218.00	
85	2	REG	\$125.00	\$250.00	
86	2	REG	\$125.00	\$250.00	

	A	B	C	D	E
87	16-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Revere Hotel	The radio shooting over to the Ritz was disconnected and out of alignment. This was causing multiple cameras in A1 to be down. Realigned the radio and got it reconnected at the Ritz. All the cameras are backup and view able.	Technician Programmer
88	16-Oct-18	WHITCOMB; SCOTT M	CIMS - BOSTON Revere Hotel	The radio shooting over to the Ritz was disconnected and out of alignment. This was causing multiple cameras in A1 to be down. Realigned the radio and got it reconnected at the Ritz. All the cameras are backup and view able.	Technician Programmer
89	18-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	Got the radio link installed at Oak Island and North Shore RD site connected from the corner to the park	Technician Programmer
90	18-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	Had to run wire on the Hyman tower roof to get their radio link up for Wonderland Circle . That link is now up and running	Technician Programmer
91	18-Oct-18	WHITCOMB; SCOTT M	CIMS - REVERE	Got the radio link installed at Oak Island and North Shore RD site connected from the corner to the park	Technician Programmer
92	19-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Lopresti Park	Site has 2 cameras and a radio that were down. We lost power at the site. The GFI needed to be replaced. We also needed a new cord cap to be put on the end of our SO cord. Got everything back up and working properly	Technician Programmer
93	19-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Lopresti Park	Site has 2 cameras and a radio that were down. We lost power at the site. The GFI needed to be replaced. We also needed a new cord cap to be put on the end of our SO cord. Got everything back up and working properly	Technician Programmer
94	19-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Walnut and Dale	The camera went down again. Went there power cycled the modem and rediscovered the camera. It's back up and recording	Technician Programmer
95	20-Oct-18	PAPPAS; SEAN M	CIMS - REVERE	Got the radio link installed at Oak Island and North Shore RD site connected from the corner to the park	Technician Programmer
96	20-Oct-18	WHITCOMB; SCOTT M	CIMS - REVERE	Had to run wire on the Hyman tower roof to get their radio link up for Wonderland Circle . That link is now up and running	Technician Programmer

	F	G	H	I	J
87	2	REG	\$109.00	\$218.00	
88	2	REG	\$109.00	\$218.00	
89	3	OT	\$125.00	\$375.00	
90	2	REG	\$109.00	\$218.00	
91	2	REG	\$109.00	\$218.00	
92	1	REG	\$109.00	\$109.00	
93	1	OT	\$125.00	\$125.00	
94	1	REG	\$109.00	\$109.00	
95	2	OT	\$125.00	\$250.00	
96	2	OT	\$125.00	\$250.00	

	A	B	C	D	E
97	20-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON	The camera being fed from the AP at Columbia and Quincy were all down. Able to get into the AP but not the station or anything past that point. We lost power at Quincy and Drayton due to a service shutdown by Eversource. We were only able to get all of our cameras back once Eversource restored the power	Technician Programmer
98	20-Oct-18	WHITCOMB; SCOTT M	CIMS - BOSTON	The camera being fed from the AP at Columbia and Quincy were all down. Able to get into the AP but not the station or anything past that point. We lost power at Quincy and Drayton due to a service shutdown by Eversource. We were only able to get all of our cameras back once Eversource restored the power	Technician Programmer
99	20-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Washington and Melville	The camera at this site was not showing video. Went and powered cycled the camera and got the video back up.	Technician Programmer
100	22-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Commons Earl of Sandwich	Replaced old PTZ camera and relanded camera on BPD Server	Technician Apprentice
101	22-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Commons Earl of Sandwich	Replaced old PTZ camera and relanded camera on BPD Server	Technician Programmer
102	22-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Washington and Melville	Old PTZ camera was bad. Replaced it with 2 fixed cameras on the existing can on the traffic AM. Assigned new Ips and landed them on the server.	Technician Apprentice
103	22-Oct-18	MARCHAND; ALEXANDER	CIMS - BOSTON Washington and Melville	Old PTZ camera was bad. Replaced it with 2 fixed cameras on the existing can on the traffic AM. Assigned new Ips and landed them on the server.	Technician Apprentice
104	22-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Washington and Melville	Old PTZ camera was bad. Replaced it with 2 fixed cameras on the existing can on the traffic AM. Assigned new Ips and landed them on the server.	Technician Programmer
105	22-Oct-18	PAPPAS; SEAN M	CIMS - BOSTON Washington and Melville	Old PTZ camera was bad. Replaced it with 2 fixed cameras on the existing can on the traffic AM. Assigned new Ips and landed them on the server.	Technician Programmer
106	22-Oct-18	PAPPAS; SEAN M	CIMS - CHELSEA Voke Park	The cameras and radio were down. Radio was bad, the port for the CAT5 was broken./ Changed out the radio and reconfigured it to talk to the AP At the Soldiers home. The camera and radio are back on line	Technician Programmer

	F	G	H	I	J
97	3	OT	\$125.00	\$375.00	
98	3	OT	\$125.00	\$375.00	
99	1	OT	\$125.00	\$125.00	
100	3	REG	\$85.00	\$255.00	
101	3	REG	\$109.00	\$327.00	
102	3	REG	\$85.00	\$255.00	
103	1	OT	\$115.00	\$115.00	
104	3	REG	\$109.00	\$327.00	
105	1	OT	\$125.00	\$125.00	
106	2	OT	\$125.00	\$250.00	

	A	B	C	D	E
107	23-Oct-18	REX II; JAMES D	CIMS - Boston D4 Fenway Cameras	Got access to BU bookstore Citgo Sign boards at the top of sign are rotted and not safe to get radio to clean domes, clean domes, check radios around Fenway.. Add fix at Sunoco station	Technician Programmer
108	23-Oct-18	REX II; JAMES D	CIMS - Boston D4 Fenway Cameras	Got access to BU bookstore Citgo Sign boards at the top of sign are rotted and not safe to get radio to clean domes, clean domes, check radios around Fenway.. Add fix at Sunoco station	Technician Programmer
109	23-Oct-18	WASHBURN; GREGORY R	CIMS - Boston D4 Fenway Cameras	Got access to BU bookstore Citgo Sign boards at the top of sign are rotted and not safe to get radio to clean domes, clean domes, check radios around Fenway.. Add fix at Sunoco station	Technician Programmer
110	23-Oct-18	REX II; JAMES D	CIMS - BOSTON Childrens Park	-children's park radio hung up ,can't access gui or pass traffic -reset radio and switch	Technician Programmer
111	23-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Childrens Park	Video traffic was not passing data at this location, reboot radio, also checked switch	Technician Programmer
112	23-Oct-18	SAVAGE;MARK	CIMS - BOSTON Fenway Monitoring	Fenway park video monitoring assistance for BPD with various issues that came about as game as going on with various cams	Technician Programmer
113	23-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Fenway Monitoring	Fenway park video monitoring assistance for BPD with various issues that came about as game as going on with various cams	Technician Programmer
114	23-Oct-18	REX II; JAMES D	CIMS - BOSTON B2 and C6-16	Cameras down after heavy rain, Columbia/Ceylon camera needed power cycle no access to pole last night	Technician Programmer
115	23-Oct-18	PAPPAS; SEAN M	CIMS - REVERE PD	Got the PTZ at Oak Island and N Shore Rd I['d and mounted/ Also go the PTZ at Bell Circle IP's and mounted as well. Waiting on licenses to land them on RPD's server	Technician Programmer
116	23-Oct-18	PAPPAS; SEAN M	CIMS - REVERE PD	Got the PTZ at Oak Island and N Shore Rd I['d and mounted/ Also go the PTZ at Bell Circle IP's and mounted as well. Waiting on licenses to land them on RPD's server	Technician Programmer
117	23-Oct-18	SAVAGE;MARK	CIMS - BOSTON	Integration CIMS cameras into Bonet system for World Series	Technician Programmer
118	23-Oct-18	SAVAGE;MARK	CIMS - BOSTON	Integration CIMS cameras into Bonet system for World Series	Technician Programmer

	F	G	H	I	J
107	8	REG	\$109.00	\$872.00	
108	1	OT	\$125.00	\$125.00	
109	8	REG	\$109.00	\$872.00	
110	1	OT	\$125.00	\$125.00	
111	1	OT	\$125.00	\$125.00	
112	4	OT	\$125.00	\$500.00	
113	3	OT	\$125.00	\$375.00	
114	4	OT	\$125.00	\$500.00	
115	1	OT	\$125.00	\$125.00	
116	2	REG	\$109.00	\$218.00	
117	1	REG	\$109.00	\$109.00	
118	3.5	OT	\$125.00	\$437.50	

	A	B	C	D	E
119	24-Oct-18	REX II; JAMES D	CIMS - BOSTON Childrens Park	-children's park radio hung up ,can't access gui or pass traffic -reset radio and switch	Technician Programmer
120	24-Oct-18	REX II; JAMES D	CIMS - BOSTON Childrens Park	-radio started acting flakey again, briefly causing one cam to drop -replace radio	Technician Programmer
121	24-Oct-18	SAVAGE;MARK	CIMS - BOSTON Fenway Monitoring	Fenway park video monitoring assistance for BPD with various issues that came about as game as going on with various cams	Technician Programmer
122	24-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Fenway Monitoring	Fenway park video monitoring assistance for BPD with various issues that came about as game as going on with various cams	Technician Programmer
123	24-Oct-18	REX II; JAMES D	CIMS - BOSTON B2 and C6-17	-10-23-18 16 plus cams dropped after heavy rain, Wayland/Dacia&hartford switches where hung up. Also C6 L st radio needed reboot	Technician Programmer
124	24-Oct-18	REX II; JAMES D	CIMS - BOSTON B2 and C6-18	10-24-18 - Columbia/Ceylon ptz needed power cycle, no access to pole last night	Technician Programmer
125	24-Oct-18	WASHBURN; GREGORY R	CIMS - BOSTON Columbia and Quincy	Resolved camera issue	Technician Programmer
126	24-Oct-18	PAPPAS; SEAN M	CIMS - CHELSEA McArdle Bridge	The PTZ was frozen. After 2 power cycles still couldn't get video back. Camera needed to come down had to reseed the ribbon connector. Also reconnect both the phoenix connector and cat5 connector. Video is back up and recording.	Technician Programmer
127	28-Oct-18	WASHBURN; GREGORY R	CIMS Boston Fenway	Fenway park video monitoring assistance for BPD with various issues that came about as game as going on with various cams	Technician Programm
128	28-Oct-18	WASHBURN; GREGORY R	CIMS Boston Harrison and Kneeland	The PTZ was down, needed hard reboot	Technician Programm
129	28-Oct-18	WASHBURN; GREGORY R	CIMS Boston Hartford and Howard	4 cameras down, found bad lan port on switch. Moved lan port of radio over 1 port on switch	Technician Programm
130	28-Oct-18	WASHBURN; GREGORY R	CIMS BHA and Babson	PTZ down found water logged. Ptz now dead from storm was instructed to install 2 new fix cameras	Technician Programm
131	29-Oct-18	PAPPAS; SEAN M	CIMS - CHELSEA Broadway and Crescent	The PTZ was frozen and showing no video. It needed a hard reset. Also reconnect the connectors at the camera as well. Its' back up and recording	Technician Programmer

	F	G	H	I	J
119	2	OT	\$125.00	\$250.00	
120	2	OT	\$125.00	\$250.00	
121	3	OT	\$125.00	\$375.00	
122	3	OT	\$125.00	\$375.00	
123	1	REG	\$109.00	\$109.00	
124	1	REG	\$109.00	\$109.00	
125	2	REG	\$109.00	\$218.00	
126	2	OT	\$125.00	\$250.00	
127	3	DT	\$145.00	\$435.00	
128	1	DT	\$145.00	\$145.00	
129	1	DT	\$145.00	\$145.00	
130	3	DT	\$145.00	\$435.00	
131	1	REG	\$109.00	\$109.00	

	A	B	C	D	E
132	30-Oct-18	REX II; JAMES D	CIMS boston BFD DOT ave	Backhaul to BHA was down after last nights upgrade, onsite found radio came unplugged when power strip got knocked off shelf, upgrade radio firmware on backhaul link	Technician Programm
133	31-Oct-18	REX II; JAMES D	CIMS Chels Pearl and Will	Found high latency on equipment past this site. Replaced ptp300 to ubnt also replaced suspect switch gathered missing equipment info for intemapper	Technician Programm
134	31-Oct-18	WaSHBURN; GREGORY R	CIMS Chels Pearl and Will	Found high latency on equipment past this site. Replaced ptp300 to ubnt also replaced suspect switch gathered missing equipment info for intemapper	Technician Programm
135	31-Oct-18	MARCHAND; ALEXANDER	CIMS Chels Broad/4th	These 2 cites needed to be taken down due to poles being moved. They have been temporarily moved until the new poles are installed	Technician Apprentice
136	31-Oct-18	MARCHAND; ALEXANDER	CIMS Chels Broad/4th	These 2 cites needed to be taken down due to poles being moved. They have been temporarily moved until the new poles are installed	Technician Apprentice
137	31-Oct-18	PAPPAS; SEAN M	CIMS Chels Broad/4th	These 2 cites needed to be taken down due to poles being moved. They have been temporarily moved until the new poles are installed	Technician Programm
138	31-Oct-18	PAPPAS; SEAN M	CIMS Chels Broad/4th	These 2 cites needed to be taken down due to poles being moved. They have been temporarily moved until the new poles are installed	Technician Programm
139	31-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS Chels Broad/4th	These 2 cites needed to be taken down due to poles being moved. They have been temporarily moved until the new poles are installed	Technician Apprentice
140	31-Oct-18	VAZQUEZ CRUZ; DEWARS	CIMS Chels Broad/4th	These 2 cites needed to be taken down due to poles being moved. They have been temporarily moved until the new poles are installed	Technician Apprentice
141	01-Nov-18	WASHBURN; GREGORY R	CIMS Bost Southie	6 cameras were down from this. At arrival to site found on intemapper everything as back up	Technician Programm
142	01-Nov-18	PAPPAS; SEAN M	CIMS Winthrop	. 1 of the fixed was down and not showing video. There was water in the can, after I dried it out and hard rebooted the camera video came back on. Now back up and recording	Technician Programm
143	03-Nov-18	REX II; JAMES D	CIMS Bost State and Congress	Link down due to noise, change frequency / channel size, upgrade sw	Technician Programm
144					
145					

	F	G	H	I	J
132	2	REG	\$109.00	\$218.00	
133	4	OT	\$125.00	\$500.00	
134	4	OT	\$125.00	\$500.00	
135	1	REG	\$85.00	\$85.00	
136	3.5	OT	\$115.00	\$402.50	
137	1	REG	\$109.00	\$109.00	
138	3.5	OT	\$125.00	\$437.50	
139	1	REG	\$85.00	\$85.00	
140	3.5	OT	\$115.00	\$402.50	
141	1.5	REG	\$109.00	\$163.50	
142	2	OT	\$125.00	\$250.00	
143	2	OT	\$125.00	\$250.00	
144	483			\$53,359.00	
145					

	A	B	C	D
1		LAN-TEL Communications, Inc.		
2		Billing for CIMS Project - Material Costs		
3		10.1.18		
4	Date of Service/Purchase	Location	Material Provided	Material Cost
5				
6		Nothing to Report		
7				
8				
9				
10				
11				
12			Total Material Costs	\$0.00

	A	B	C	D	E	F
1			LAN-TEL Communications, Inc.			
2			Billing for CIMS Project - Project Management Costs			
3			10.1.18			
4	Date of Service	Location	Work Performed	# Hours	Rate	Total
5	10/2/2018	Various Locations	Check Network, Project Management, Respond to POC calls and emails	1.5	\$98.00	\$147.00
6	10/10/2018	Various Locations	Check Network, Project Management, Respond to POC calls and emails	2	\$98.00	\$196.00
7	10/18/2018	Various Locations	Check Network, Project Management, Respond to POC calls and emails	2	\$98.00	\$196.00
8	10/24/2018	Various Locations	Check Network, Project Management, Respond to POC calls and emails	1.5	\$98.00	\$147.00
9	10/30/2018	Various Locations	Check Network, Project Management, Respond to POC calls and emails	2	\$98.00	\$196.00
10			Total	9		\$882.00

	G
1	
2	
3	
4	Special Event, PSNET or CIMS
5	
6	
7	
8	
9	
10	

	A	B	C	D
1	October Labor Totals			
2	Labor Type	Hours	Total	
3	LAN-TEL Labor regular rate	226.5	\$24,688.50	
4	LAN-TEL Labor overtime rate	111.5	\$13,937.50	
5	LAN-TEL Labor double time rate	8	\$1,160.00	
6	LAN-TEL Labor Apprentice regular rate	64	\$5,440.00	
7	LAN-TEL Labor Apprentice overtime rate	8	\$920.00	
8	LAN-TEL Software Tech rate	16	\$2,000.00	
9	LAN-TEL Software Tech overtime rate	5	\$725.00	
10	LAN-TEL Software Tech double time rate	0	\$0.00	
11	Sonet	44	\$4,488.00	
12	Total Labor	483	\$53,359.00	
13				
14	Total Project Management Labor	9	\$882.00	
15	Total Labor & PM			\$54,241.00
16	October Material Totals			
17	Total PTZ DvTel Cameras	0	\$0.00	
18	Total Fixed DvTel Cameras	0	\$0.00	
19	Total Power Supplies	0	\$0.00	
20	Total Bucket Truck Rentals (LAN-TEL & Sonet)	0	\$0.00	
21	Total Adapters	0	\$0.00	
22	Total Encoders	0	\$0.00	
23	Total NEMA Enclosures	0	\$0.00	
24	Total Astro Brackets	0	\$0.00	
25	Total Antennas & Assoc. Equipment	0	\$0.00	
26	Total Cable & Assoc. Hardware	-	\$0.00	
27	Total POEs	0	\$0.00	
28	Total Misc. Equipment	-	\$0.00	
29	Total Material Used			\$0.00
30				
31	Total Billing for October Billing			\$54,241.00