

	A	B	C	D	E	F	G	H	I	J	K	L	M
1	<b>Boston Police Department Detention Cell Project Consolidated Weekly Summary</b>												
2													
3		<b>BK</b>	<b>Q</b>	<b>S</b>	<b>E</b>	<b>C6</b>	<b>C11</b>	<b>D4</b>	<b>D14</b>	<b>E5</b>	<b>E13</b>	<b>E18</b>	<b>HANCOCK</b>
4	<b>Video Storage and Workstations</b>												
5	Storage Server	1											
6	Video Workstation												
7													
8	<b>IP Video</b>												
9	Fixed IP Camera							X	X	X	X	X	
10	PTZ IP Camera	11											X
11	Antennas	22			X	X	X	X	X	X	X	X	
12													
13													
14													
15													
16	<b>Network</b>												
17	IP Addresses	X					X	X	X	X	x	x	
18	Wiring					X	X	X	X	X	X	X	x
19													
20													
21	<b>VIK-E-40SS-EWP</b>												
22		<b>RY-PA</b>											
23		<b>VG-224</b>											
24		<b>PS-1225UL</b>											
25		<b>Talk-Alert</b>											
26													
27													
28													
29													
30													
31													
32													
33													
34													
35													
36													
37													
38													
39													
40													
41													
42													

	A	B	C	D	E
1	<b>Brookline Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address Camera</b>
4	Storage Server	1	Dell	USS-ENT-20R5-16	
5	Video Workstation	0			
6	Fixed IP Camera				
7	PTZ IP Camera	11	Dvtel	CP-4221-301	
8	Antenna	22	Ubiquity	NSM5 US	
9					
10					
11					
12	<b>CAMERA LOCATION</b>				
13	Beacon -Carlton	1	Dvtel	CP-4221-301	
14	Beacon -Harvard	1	Dvtel	CP-4221-301	
15	Beacon-St Paul	1	Dvtel	CP-4221-301	
16	Beacon-Washington	1	Dvtel	CP-4221-301	
17	Beacon -Chestnut hill	1	Dvtel	CP-4221-301	
18	Boylston-Chestnut Hill	1	Dvtel	CP-4221-301	
19	Boylston Hammond	1	Dvtel	CP-4221-301	
20	Boylston-Cypress	1	Dvtel	CP-4221-301	
21	Boylston-High	1	Dvtel	CP-4221-301	
22	Boylston-Summer	1	Dvtel	CP-4221-301	
23	Boylston-Aspinwall	0	Dvtel	CP-4221-301	
24	St. Paul -Longwood	1	Dvtel	CP-4221-301	
25					
26					
27					
28					
29					
30					
31					
32	<b>SUBNET</b>	<b>10.0.80.1</b>			
33	<b>MASK</b>	<b>255.255.255.0</b>			
34	<b>DEFAULT GATEWAY</b>				
35	<b>IP RANGE</b>				
36					
37					
38					
39					
40					
41					
42					
43					
44					

	F	G	H	I	J
1					
2					
3	<b>IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>
4					
5					
6					
7					
8					
9					
10					
11					
12					
13	10.0.65.34	10.0.65.33	10.0.65.31	Admin / CofffeeMilk	Admin / Mbhsr
14	10.0.80.107	10.10.80.105	10.10.80.104	Admin/CoffeeMilk	Admin /Mbhsr
15	10.0.80.105	10.10.80.107	10.10.80.106	Admin/CoffeeMilk	Admin /Mbhsr
16	10.0.80.113	10.10.80.113	10.10.80.112	Admin/CoffeeMilk	Admin /Mbhsr
17	10.0.80.111	10.10.80.111	10.10.80.110	Admin/CoffeeMilk	Admin /Mbhsr
18	10.0.80.121	10.10.81.103	10.10.81.102	Admin/CoffeeMilk	Admin /Mbhsr
19	10.0.80.140	NO ANTENNA	NO ANTENNA	Admin/CoffeeMilk	Admin /Mbhsr
20	10.0.80.101	10.10.80.115	10.10.80.114	Admin/CoffeeMilk	Admin /Mbhsr
21	10.0.80.115	10.10.80.101	10.10.80.100	Admin/CoffeeMilk	Admin /Mbhsr
22	10.0.80.117	10.10.80.117	10.10.80.116	Admin/CoffeeMilk	Admin /Mbhsr
23	10.0.81.102	10.10.81.101	10.10.81.100	Admin/CoffeeMilk	Admin /Mbhsr
24	10.0.80.109	10.10.80.109	10.10.80.108	Admin/CoffeeMilk	Admin /Mbhsr
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	K	L
1		
2		
3	Installed	
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		

	A	B	C	D	E
1	<b>Quincy Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	1	Dell	USS-ENT-20R5-16	B8-2A-72-D2-FA-15
5	Video Workstation				
6	Fixed IP Camera				
7	PTZ IP Camera	10	Dvtel	CP-4221-301	
8	Antenna	20	Ubiquity	NSM5 US	
9					
10	<b>CAMERA LOCATION</b>				
11	100 Hancock	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-89
12	1400 Hancock	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-5D
13	95 West Squantum	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-89
14	Marina Bay	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-76
15	O'Brien Towers	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-69
16	QHS	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-62
17	QMC	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-71
18	QPD Front	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-81
19	QPD Roof	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-5D
20	QMC 2	1	Dvtel	CP-4221-301	00-1B-D8-80-4D-6C
21					
22	10.0.68.1-254				
23	255.255.255.0				
24	10.0.68.1				
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	F	G	H	I	J
1					
2					
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>
4	10.0.68.201				
5					
6					
7					
8					
9					
10					
11	10.0.68.117	10.10.68.103	10.10.68.102	Admin / CofffeeMilk	Admin / Mbhsr
12	10.0.68.109	10.10.68.109	10.10.68.108	Admin/CoffeeMilk	Admin /Mbhsr
13	10.0.68.105	10.10.68.105	10.10.68.104	Admin/CoffeeMilk	Admin /Mbhsr
14	10.0.68.97	10.10.68.101	10.10.68.100	Admin/CoffeeMilk	Admin /Mbhsr
15	10.0.68.112	10.10.68.111	10.10.68.110	Admin/CoffeeMilk	Admin /Mbhsr
16	10.0.68.107	10.10.68.113	10.10.68.112	Admin/CoffeeMilk	Admin /Mbhsr
17	10.0.68.115	10.10.68.107	10.10.68.106	Admin/CoffeeMilk	Admin /Mbhsr
18	10.0.68.8	NO ANT	NO ANT	Admin/CoffeeMilk	Admin /Mbhsr
19	10.0.68.125	NO ANT	NO ANT	Admin/CoffeeMilk	Admin /Mbhsr
20	10.0.68.143	SEE QMC	See QMC	Admin/CoffeeMilk	Admin /Mbhsr
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	K	L
1		
2		
3	Installed	
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		

	A	B	C	D	E
1	<b>Somerville Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	1	Dell	USS-ENT-20R5-16	
5	Video Workstation				
6	Fixed IP Camera	4	Dvtel	CM-6208-11-I	
7	PTZ IP Camera	6	Dvtel	CP-4221-301	
8	Antenna	16	Ubiquity	NSM5 US	
9					
10					
11					
12	<b>CAMERA LOCATION</b>				
13	165 Broadway	1	Dvtel	CP-4221-301	
14	25 Highland 1	1	Dvtel	CP-4221-301	
15	La Quinta 1	1	Dvtel	CP-4221-301	
16	La Quinta 2	1	Dvtel	CP-4221-301	
17	Union Sq	1	Dvtel	CP-4221-301	
18	Thorndike 1	1 F	Dvtel	CM-6208-11-I	
19	Thorndike 2	1 F	Dvtel	CM-6208-11-I	
20	Holland 1	1 F	Dvtel	CM-6208-11-I	
21	Holland 2	1 F	Dvtel	CM-6208-11-I	
22	Davis Sq	1	Dvtel	CP-4221-301	
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36	<b>SUBNET</b>	<b>255.255.255.0</b>			
37	<b>MASK</b>				
38	<b>DEFAULT GATEWAY</b>	<b>10.0.84.1</b>			
39	<b>IP RANGE</b>	<b>10.0.84.1 -10.0.84.254 Cameras</b>			
40		<b>10.10.84.1-10.10.84.254-Antennas</b>			
41					
42					
43					
44					



	F	G	H	I	J	K
1						
2						
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>	<b>Installed</b>
4	10.0.80.200					
5						
6						
7						
8						
9						
10						
11						
12						
13	10.0.83.103	10..10.83.103		Admin / CofffeeMilk	Admin / Mbhsr	
14	10.0.83.111	NO ANT		Admin/CoffeeMilk	Admin /Mbhsr	
15	10.0.83.101	10.0.83.101		Admin/CoffeeMilk	Admin /Mbhsr	
16	10.0.83.133	TBA		Admin/CoffeeMilk	Admin /Mbhsr	
17	10.0.84.101	10.0.84.101		Admin/CoffeeMilk	Admin /Mbhsr	
18	10.0.83.107	10.0.83.107		Admin/CoffeeMilk	Admin /Mbhsr	
19	10.0.83.108	Same as above		Admin/CoffeeMilk	Admin /Mbhsr	
20	10.0.83.109	10.0.83.109		Admin/CoffeeMilk	Admin /Mbhsr	
21	10.0.83.110	Same as above		Admin/CoffeeMilk	Admin /Mbhsr	
22	10.0.83.105	10.10.83.105		Admin/CoffeeMilk	Admin /Mbhsr	
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						

	A	B	C	D	E
1	<b>Everett Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	2	Dell	USS-ENT-24R5-20	
5	Video Workstation				
6	Fixed IP Camera	6	Dvtel	CM-6208-11-I	
7	PTZ IP Camera	11	Dvtel	CP-4221-301	
8	Antenna	28	Ubiquity	NSM5 US	
9					
10					
11					
12	<b>CAMERA LOCATION</b>				
13	Ferry St 1	1 F	Dvtel	CM-6208-11-I	
14	Ferry St 2	1 F	Dvtel	CM-6208-11-I	
15	Ferry St 3	1 F	Dvtel	CM-6208-11-I	
16	MBTA Waterway	1	Dvtel	CP-4221-301	
17	Mystic Tower	1	Dvtel	CP-4221-301	
18	Mystic Tower	1	Dvtel	CP-4221-301	
19	Parlin Jr High	1	Dvtel	CP-4221-301	
20	Everett Sq	1 F	Dvtel	CM-6208-11-I	
21	Everett Sq	1 F	Dvtel	CM-6208-11-I	
22	Everett Sq	1 F	Dvtel	CM-6208-11-I	
23	RBP West	1	Dvtel	CP-4221-301	
24	St Lawrence	1	Dvtel	CP-4221-301	
25	Sweetzer 1	1	Dvtel	CP-4221-301	
26	Sweetzer 2	1	Dvtel	CP-4221-301	
27	Target 1	1	Dvtel	CP-4221-301	
28	Target 2	1	Dvtel	CP-4221-301	
29	Everett Commons	1	Dvtel	CP-4221-301	
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	F	G	H	I	J	K
1						
2						
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>	<b>Installed</b>
4	10.0.80.200					
5						
6						
7						
8						
9						
10						
11						
12						
13	10.0.73.112	10.10.73.106	10.10.73.107	Admin / CofffeeMilk	Admin / Mbhsr	
14	10.0.73.111	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
15	10.0.73.110	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
16	10.0.72.119	10.10.72.119	10.10.72.118	Admin/CoffeeMilk	Admin /Mbhsr	
17	10.0.72.135	10.10.72.120	10.10.72.121	Admin/CoffeeMilk	Admin /Mbhsr	
18	10.0.73.136	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
19	10.0.73.99	10.0.73.101	10.0.73.101	Admin/CoffeeMilk	Admin /Mbhsr	
20	10.0.72.138	10.10.72.103	10.10.72.102	Admin/CoffeeMilk	Admin /Mbhsr	
21	10.0.72.141	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
22	10.0.72.143	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
23	10.0.72.117	10.10.72.115	10.10.72.114	Admin / CofffeeMilk	Admin / Mbhsr	
24	10.0.72.134	10.10.72.140	10.10.72.145	Admin/CoffeeMilk	Admin /Mbhsr	
25	10.0.72.131	10.10.72.101	10.10.72.100	Admin/CoffeeMilk	Admin /Mbhsr	
26	10.0.72.137	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
27	10.0.72.132	10.10.72.173	10.10.72.110	Admin/CoffeeMilk	Admin /Mbhsr	
28	10.0.72.192	SAME	SAME	Admin/CoffeeMilk	Admin /Mbhsr	
29	10.0.72.130	10.10.72.104	10.10.72.105	Admin/CoffeeMilk	Admin /Mbhsr	
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						

	A	B	C	D	E
1	<b>Revere Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	1	Dell	USS-ENT-20R5-16	
5	Video Workstation				
6	Fixed IP Camera				
7	PTZ IP Camera	15	Dvtel	CP-4221-301	
8	Antenna	30	Ubiquity	NSM5 US	
9					
10	<b>CAMERA LOCATION</b>				
11	300 Ocean Ave E	1	Dvtel	CP-4221-301	
12	300 Ocean Ave W	1	Dvtel	CP-4221-301	
13	Beachmont	1	Dvtel	CP-4221-301	
14	Broadway Tower	1	Dvtel	CP-4221-301	
15	Comfort Inn East	1	Dvtel	CP-4221-301	
16	Comfort Inn West	1	Dvtel	CP-4221-301	
17	Hampton Inn	1	Dvtel	CP-4221-301	
18	Hyman Twr@Beach	1	Dvtel	CP-4221-301	
19	Hyman Twr@Shirley	1	Dvtel	CP-4221-301	
20	Malden @ Broadway	1	Dvtel	CP-4221-301	
21	Revere FD	1	Dvtel	CP-4221-301	
22	Revere HS	1	Dvtel	CP-4221-301	
23	Seaview Towers E	1	Dvtel	CP-4221-301	
24	Seaview Towers W	1	Dvtel	CP-4221-301	
25	Sigourney -Squire	1	Dvtel	CP-4221-301	
26					
27				10.0.76.200	
28				255.255.255.0	
29				10.0.76.1	
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	F	G	H	I	J	K
1						
2						
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>	<b>Installed</b>
4	10.0.68.200					
5						
6						
7						
8						
9						
10						
11	10.0.75.121	10.10.75.109	10.10.75.108	Admin / CofffeeMilk	Admin / Mbhsr	
12	10.0.75.109	Same as above	Same as above	Admin/CoffeeMilk	Admin /Mbhsr	
13	10.0.76.103	10.10.76.103	10.10.76.102	Admin/CoffeeMilk	Admin /Mbhsr	
14	10.0.75.113	NO ANTENNA	NO ANTENNA	Admin/CoffeeMilk	Admin /Mbhsr	
15	10.0.75.103	10.10.75.103	10.10.75.102	Admin/CoffeeMilk	Admin /Mbhsr	
16	10.0.75.135	Same as above	Same as above	Admin/CoffeeMilk	Admin /Mbhsr	
17	10.0.76.101	10.10.76..101	10.10.76.100	Admin/CoffeeMilk	Admin /Mbhsr	
18	10.0.75.117	10.10.75.111	10.10.75.110	Admin/CoffeeMilk	Admin /Mbhsr	
19	10.0.75.119	Same as above	Same as above	Admin/CoffeeMilk	Admin /Mbhsr	
20	10.0.75.101	10.0.75.101	10.10.75.100	Admin/CoffeeMilk	Admin /Mbhsr	
21	10.0.75.115	Fiber	Fiber	Admin / CofffeeMilk	Admin /Mbhsr	
22	10.0.75.111	10.10.75.107	10.10..75.106	Admin/CoffeeMilk	Admin /Mbhsr	
23	10.0.75.81	10.10.75.81	10.10.75.80	Admin/CoffeeMilk	Admin /Mbhsr	
24	10.0.75.83	Same as above	Same as above	Admin/CoffeeMilk	Admin /Mbhsr	
25	10.0.75.107	10.10.75.113	10.10.75.112	Admin/CoffeeMilk	Admin /Mbhsr	
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						

	A	B	C	D	E
1	<b>Revere Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	1	Dell	USS-ENT-12R5-09	
5	Video Workstation				
6	Fixed IP Camera				
7	PTZ IP Camera	7	Dvtel	CP-4221-301	
8	Antenna	14	Ubiquity	NSM5 US	
9					
10	<b>CAMERA LOCATION</b>				
11	Fort Banks	1	Dvtel	CP-4221-301	
12	MaGees Corner	1	Dvtel	CP-4221-301	
13	Revere And Crest	1	Dvtel	CP-4221-301	
14	Revere Beach Pump	1	Dvtel	CP-4221-301	
15	Winthrop FD	1	Dvtel	CP-4221-301	
16	Winthrop HS	1	Dvtel	CP-4221-301	
17	Winthrop Water Tower	1	Dvtel	CP-4221-301	
18					
19	10.0.78.200				
20	255.255.255.0				
21	10.0.78.1				
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	F	G	H	I	J	K
1						
2						
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>	<b>Installed</b>
4	10.0.68.200					
5						
6						
7						
8						
9						
10						
11	10.10.79.109			Admin / CofffeeMilk	Admin / Mbhsr	
12	NA	NA	NA	Admin/CoffeeMilk	Admin /Mbhsr	
13	10.10.79.113	10.10.79.113	10.10.79.112	Admin/CoffeeMilk	Admin /Mbhsr	
14	10.0.79.111	10.10.79.111	10.10.79.112	Admin/CoffeeMilk	Admin /Mbhsr	
15	10.0.78.101	10.10.78.101	10.10.78.100	Admin/CoffeeMilk	Admin /Mbhsr	
16	NA	NA	NA	Admin/CoffeeMilk	Admin /Mbhsr	
17	10.0.79.101	No Antenna	No Antenna	Admin/CoffeeMilk	Admin /Mbhsr	
18				Admin/CoffeeMilk	Admin /Mbhsr	
19				Admin/CoffeeMilk	Admin /Mbhsr	
20				Admin/CoffeeMilk	Admin /Mbhsr	
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						

	A	B	C	D	E
1	<b>Chelsea Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	3	Dell	USS-ENT-24R5-20	
5	Video Workstation				
6	Fixed IP Camera				
7	PTZ IP Camera	35	Dvtel	CP-4221-301	
8	Antenna	98	Ubiquity	NSM5 US	
9					
10	<b>CAMERA LOCATION</b>				
11	260 Clark	1	Dvtel	CP-4221-301	
12	Arlington @ 6th	1	Dvtel	CP-4221-301	
13	Arlington St	1	Dvtel	CP-4221-301	
14	Beacham St @ DD's	1	Dvtel	CP-4221-301	
15	Beacham (NEPC)	1	Dvtel	CP-4221-301	
16	Bellingham Sq		Dvtel	CP-4221-301	
17	Bossom Park	1	Dvtel	CP-4221-301	
18	Broadway @ Marlboro		Dvtel	CP-4221-301	
19	Boadway @ 2nd		Dvtel	CP-4221-301	
20	Broadway @ 3rd	1	Dvtel	CP-4221-301	
21	Broadway @4th	1	Dvtel	CP-4221-301	
22	Broadway @5th		Dvtel	CP-4221-301	
23	Bway@Hawthorne		Dvtel	CP-4221-301	
24	Bway @ Williams TC		Dvtel	CP-4221-301	
25	Bway-Williams CC		Dvtel	CP-4221-301	
26	Bway Upper		Dvtel	CP-4221-301	
27	Bway -Webster N	1	Dvtel	CP-4221-301	
28	Bway -WebsterS	1	Dvtel	CP-4221-301	
29	Carter St Ramp	1	Dvtel	CP-4221-301	
30	Cary Sq		Dvtel	CP-4221-301	
31	Central-Hawthorne	1	Dvtel	CP-4221-301	
32	Chestnut-4th	1	Dvtel	CP-4221-301	
33	Chestnut-Beacon	1	Dvtel	CP-4221-301	
34	Everett@Spruce	1	Dvtel	CP-4221-301	
35	Everett @ MGH	1	Dvtel	CP-4221-301	
36	Fay Sq		Dvtel	CP-4221-301	
37	Highland -Gerrish	1	Dvtel	CP-4221-301	
38	Highland Park 1	1	Dvtel	CP-4221-301	
39	Library -Highland	1	Dvtel	CP-4221-301	
40	Library Pocket		Dvtel	CP-4221-301	
41	Luther Place Fixed	1	Dvtel	CP-4221-301	
42	Luther Place PTZ	1	<b>Dvtel</b>	CP-4221-301	
43	Luther Place Walk	1	Dvtel	CP-4221-301	
44	Meridian St Bridge	1	Dvtel	CP-4221-301	



	F	G	H	I	J	K
1						
2						
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>	<b>Installed</b>
4	10.0.68.200					
5						
6						
7						
8						
9						
10						
11	10.0.74.92	10.10.74.241	10.0.74.247	Admin / CofffeeMilk	Admin / Mbhsr	
12	10.0.74.11	10.10.74.111	10.10.74.110	Admin/CoffeeMilk	Admin /Mbhsr	
13	10.0.74.109	10.10.74.109	10.10.74.108	Admin/CoffeeMilk	Admin /Mbhsr	
14	10.0.74.103	10.10.74.101	10.10.74.100	Admin/CoffeeMilk	Admin /Mbhsr	
15	10.0.74.101	10.10.74.103	10.10.74.102	Admin/CoffeeMilk	Admin /Mbhsr	
16		10.0.87.12	10.0.87.9	Admin/CoffeeMilk	Admin /Mbhsr	
17	10.0.87.149	10.0.87.17	10.0.87.19	Admin/CoffeeMilk	Admin /Mbhsr	
18		10.0.87.165	10.0.87.163	Admin/CoffeeMilk	Admin /Mbhsr	
19		10.0.77.160	10.0.77.131	Admin/CoffeeMilk	Admin /Mbhsr	
20	10.0.87.153	10.0.87.104	10.0.87.103	Admin/CoffeeMilk	Admin /Mbhsr	
21	10.0.87.126	10.0.87.125	10.0.87.124	Admin / CofffeeMilk	Admin / Mbhsr	
22		10.0.87.18	10.0.87.16	Admin/CoffeeMilk	Admin /Mbhsr	
23		10.0.87.100	10.0.87.137	Admin/CoffeeMilk	Admin /Mbhsr	
24		10.0.77.237	10.0.77.132	Admin/CoffeeMilk	Admin /Mbhsr	
25		TBA	TBA	Admin/CoffeeMilk	Admin /Mbhsr	
26		SAME AS 260 Clark	Same as 260 Clark	Admin/CoffeeMilk	Admin /Mbhsr	
27	10.0.74.161	10.0.74.81	10.0.74.80	Admin/CoffeeMilk	Admin /Mbhsr	
28	10.0.74.162	Same as above	Same as above	Admin/CoffeeMilk	Admin /Mbhsr	
29	10.0.74.105	FIBER	Fiber	Admin/CoffeeMilk	Admin /Mbhsr	
30		10.0.74.237	10.0.74.249	Admin/CoffeeMilk	Admin /Mbhsr	
31	10.0.77.198	10.0.77.133	10.0.77.131	Admin / CofffeeMilk	Admin / Mbhsr	
32	10.0.87.130	10.0.87.131	10.0.87.129	Admin/CoffeeMilk	Admin /Mbhsr	
33	10.0.74.190	10.0.77.134	10.0.77.135	Admin/CoffeeMilk	Admin /Mbhsr	
34	10.0.74.243	10.0.74.243	10.0.74.249	Admin/CoffeeMilk	Admin /Mbhsr	
35	10.0.87.146	10.0.87.146	10.0.87.147	Admin/CoffeeMilk	Admin /Mbhsr	
36	TBA	TBA	TBA	Admin/CoffeeMilk	Admin /Mbhsr	
37	10.0.74.131	NO Antenna	NO Antenna	Admin/CoffeeMilk	Admin /Mbhsr	
38	10.0.77.140	10.0.77.238	10.0.77.245	Admin/CoffeeMilk	Admin /Mbhsr	
39	10.0.74.130	No Antenna	NO antenna	Admin/CoffeeMilk	Admin /Mbhsr	
40		NO Antenna	NO Antenna	Admin/CoffeeMilk	Admin /Mbhsr	
41	10.0.87.21	10.0.87.11	10.0.87.8	Admin/CoffeeMilk	Admin /Mbhsr	
42	10.0.87.121	10.0.87.101	10.0.87.101	Admin/CoffeeMilk	Admin /Mbhsr	
43	10.0.87.123	Same as above	Same as above	Admin / CofffeeMilk	Admin / Mbhsr	
44	10.0.77.149	10.0.77.240	10.0.77.241	Admin/CoffeeMilk	Admin /Mbhsr	

	A	B	C	D	E
45	MWRA Highland Park	1	Dvtel	CP-4221-301	
46	MWRA Tower	1	Dvtel	CP-4221-301	
47	Park and Congress	1	Dvtel	CP-4221-301	
48	Pearl -Williams	1	Dvtel	CP-4221-301	
49	Prattville Park 1 F	1	Dvtel	CP-4221-301	
50	Prattville Park 2 PTZ		Dvtel	CP-4221-301	
51	Ruiz Park		Dvtel	CP-4221-301	
52	Shawmut-Chester	1	Dvtel	CP-4221-301	
53	Soldiers Home S	1	Dvtel	CP-4221-301	
54	Soldiers Home N CVS	1	Dvtel	CP-4221-301	
55	Spruce -6th	1	Dvtel	CP-4221-301	
56	Tobin Bridge	1	Dvtel	CP-4221-301	
57	Williams -Spruce				
58	Beacom and Chestnut	1	Dvtel	CP-4221-301	
59	Forbes River		1 Dvtel	CP-4221-301	
60	Gulff Oil				
61					
62					
63					
64					

	F	G	H	I	J	K
45	10.0.77.250	10.0.77.252	Backhaul	Admin/CoffeeMilk	Admin /Mbhsr	
46	TBA	TBA	TBA	Admin/CoffeeMilk	Admin /Mbhsr	
47	10.0.87.157	10.0.87.14	10.0.87.13	Admin/CoffeeMilk	Admin /Mbhsr	
48	10.0.77.143	10.10.77.101	10.10.77.100	Admin/CoffeeMilk	Admin /Mbhsr	
49	10.0.74.115	10.0.74.238	10.0.74.245	Admin/CoffeeMilk	Admin /Mbhsr	
50		Same as above	Same as above	Admin/CoffeeMilk	Admin /Mbhsr	
51		NA	NA	Admin/CoffeeMilk	Admin /Mbhsr	
52	10.0.87.142	10.0.87.141	10.0.87.139	Admin/CoffeeMilk	Admin /Mbhsr	
53		Backhaul	BackHaul	Admin/CoffeeMilk	Admin /Mbhsr	
54	10.0.74.84	Backhaul	Backhaul	Admin/CoffeeMilk	Admin /Mbhsr	
55	TBA	TBA	TBA	Admin / CoffeeMilk	Admin / Mbhsr	
56	TBA	TBA	TBA	Admin/CoffeeMilk	Admin /Mbhsr	
57	10.0.74.24	10.0.74.236	10.0.74.235	Admin/CoffeeMilk	Admin /Mbhsr	
58						
59						
60						
61						
62						
63						
64						

	A	B	C	D	E
1	<b>Chelsea Upgrade</b>				
2					
3	<b>Deliverables</b>	<b>Quantity</b>	<b>Manufacturer</b>	<b>Model</b>	<b>MAC Address</b>
4	Storage Server	0	Dell	USS-ENT-20R5-16	
5	Video Workstation				
6	Fixed IP Camera				
7	PTZ IP Camera	10	Dvtel	CP-4221-301	
8	Antenna	20	Ubiquity	NSM5 US	
9					
10	<b>CAMERA LOCATION</b>				
11		1	Dvtel	CP-4221-301	
12		1	Dvtel	CP-4221-301	
13		1	Dvtel	CP-4221-301	
14		1	Dvtel	CP-4221-301	
15		1	Dvtel	CP-4221-301	
16		1	Dvtel	CP-4221-301	
17		1	Dvtel	CP-4221-301	
18		1	Dvtel	CP-4221-301	
19		1	Dvtel	CP-4221-301	
20		1	Dvtel	CP-4221-301	
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					

	F	G	H	I	J	K
1						
2						
3	<b>Camera IP</b>	<b>Antenna Slave</b>	<b>Antenna Master</b>	<b>Camera Password</b>	<b>Antenna Password</b>	<b>Installed</b>
4	10.0.68.200					
5						
6						
7						
8						
9						
10						
11				Admin / CofffeeMilk	Admin / Mbhsr	
12				Admin/CoffeeMilk	Admin /Mbhsr	
13				Admin/CoffeeMilk	Admin /Mbhsr	
14				Admin/CoffeeMilk	Admin /Mbhsr	
15				Admin/CoffeeMilk	Admin /Mbhsr	
16				Admin/CoffeeMilk	Admin /Mbhsr	
17				Admin/CoffeeMilk	Admin /Mbhsr	
18				Admin/CoffeeMilk	Admin /Mbhsr	
19				Admin/CoffeeMilk	Admin /Mbhsr	
20				Admin/CoffeeMilk	Admin /Mbhsr	
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						